

POINTS

- It can be change the working time to flexibility at per each process area.
- Maintenance is easily possible.
- OPOSSIBLE to make the facilities plan that the nothing dead zone places.



Main Specification ■Work weight Max.150kg(at horizontal transfer) Max.30kg (at up/down transfer and 30 degree) ■ Transfer speed Max.12m/min. 184 Min.800mm turning radius ■ Vertical rail ■ Horizontal rail Min.800mm turning radius ■ Transfer pitch Upper than 400mm (* x 200mm) 30 degree ■ Max. slope angle ■Up/down feeder device ■Index device Ö. ■Turn device ■ Transfer device ■ Drop & Lift device ■ Divergence & Junction device